



PACKAGING INSTRUCTIONS:

1. PRINT LABEL USING PART NUMBER.
2. FOLD INSTRUCTION SHEET TWICE.
3. PACK ALL ITEMS IN BAG & HEAT SEAL AS SHOWN.
4. APPLY LABEL TO BAG.



- LABEL ON BAG.
1. NOT ALL WASHERS ARE NEEDED FOR INSTALLATION, SEE INSTRUCTION (6271-280) INCLUDED IN KIT.
  2. \*'C' RING ONLY USED WITH ARMOR.

SYM	DESCRIPTION	DATE	DWN	APPD
H	ADDED PART NAMES, 'C' RING NOTE & ASSEMBLY VIEW. ECN# E3264	7-20-09	DW	LK
G	DELETED 1 SEALING WASHER FROM KIT. ECN#E0793	6-1-04	S.R.	JJM
F	DELETED UE LOGO & ADDRESS FROM PKG. INSTR. 1. ECN# C8628	3/22/00	PLW	L.K.
E	REVISED PACKAGING INSTRUCTIONS WAS STAMP PERFORM BOARD. ECN#C8113	5/24/99	P.W.	JJM
D	DELETED COMPRESSION NUT FROM VIEW. ECN#C7121	2-20-98	P.W.	A.M.
C	REDRAWN. GENERAL REVISION PER ECN#C6285	3-12-97	P.W.	J.J.M.
REVISIONS				

ORIGINAL DATE	2-24-94
DRWN	A.EBALO
CHKD	PETER WEILER
APPD	J.MONDELLO
UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES	
TOLERANCES ON FRACTIONS ±1/64	
2 PLACE DEC 3 PLACE DEC ANGLES ±0.010 ±0.005 ±1/2°	
DO NOT SCALE THIS DRAWING	

TITLE	SEALING ACCESSORIES KIT
SCALE	HALF

DF001D	UNITED ELECTRIC CONTROLS COMPANY WATERTOWN * MASSACHUSETTS
DWG NO	SD6213-318